



GOVERNOR TERRY E. BRANSTAD
LT. GOVERNOR KIM REYNOLDS

ELIZABETH S. JACOBS, CHAIR
DARRELL HANSON, BOARD MEMBER
SWATI A. DANDEKAR, BOARD MEMBER

January 24, 2013
File: E-20994, Amendment 11
Re: Deficiency Letter No. 2

BrownWinick Attorneys At Law
Attn.: Leanna D. Whipple
666 Grand Avenue, Suite 2000
Des Moines, IA 50309

Dear Ms. Whipple:

Staff review of your responses filed on December 19, 2012, has identified some deficiencies, which must be corrected for processing to continue.

1. Exhibit C – Segment 1 of 3 (no ub)

Structure drawing 69D2V3. In addressing item 3.b. of previous deficiency letter (December 6, 2012), you changed the suspension dead-end insulator (see page 1, line 18, far right column). However, in the above structure drawing, a separation of conductor to pole/pole surface found not consistent with that of structure drawing 69ALV3, and of page 1, line 18 (far right column). Please revise.

2. Exhibit C – Segment 2 of 3 (with IPL 7.2 kV single phase ub)

Structure drawing 69D2V3. See comment in 1. above, and revise.

3. Exhibit C – Segment 3 of 3 (with IPL 12.5 kV ub)

a. Page 3, line 56, last filled-in blank. Please revise by adding the 10-foot crossarm (see underbuild structure drawing 10U-1D/10U-1V, and 10U-4Y).

b. Structure drawing 69D2V3. Refer to 1. above, and revise.

If you have any questions, feel free to contact me at 515-725-7339 or at bao.nguyen@iub.iowa.gov

Sincerely,

/s/ Bao Nguyen

Bao Nguyen
Utilities Regulation Engineer
Safety and Engineering Section